

No	Position / Role	Educational Qualification	Competencies & Certificates	Work Experience (Petrochemical / Oil & Gas)	By ORYX GTL	By Contractor	Permit-To-Work Level Required
1	<b>Mechanical Supervisor</b>	<ul style="list-style-type: none"> <li>• BE - Mech. Eng'g.</li> <li>• Diploma in Mech. Eng'g.</li> </ul>	<ul style="list-style-type: none"> <li>• Work Experience certificates</li> <li>• Able to communicate in English</li> <li>• Must demonstrate to be comfortable to provide unambiguous instructions in English</li> <li>• Identify the spares and resource requirements and preparation of workpacks.</li> <li>• Interpreting technical documents( P&amp;ID's , Isometrics, Drawings, inspection sketches etc)</li> <li>• Ability to prepare documents like method statements and JHA,</li> </ul>	<ul style="list-style-type: none"> <li>• Min. 8 - 10 years on related field (To be supported by CV and employment certificates)</li> <li>• Minimum 3 years' experience in permit-to-work system as receiver.</li> <li>• Refer the Job Description for more details</li> </ul>	<ul style="list-style-type: none"> <li>&gt; PTW- 1 and PTW-2 Training</li> <li>&gt; ORYX GTL's Plant &amp; Safety Orientation</li> <li>&gt; Confined Space Entry Awareness</li> <li>&gt; Job Hazard Assessment Training</li> <li>&gt; Lifting &amp; Rigging Awareness</li> <li>&gt; PPE Awareness Training</li> <li>&gt; Excavation &amp; Trenching Safety Training</li> <li>&gt; Heat Stress Awareness</li> <li>&gt; ISPS Awareness (Port Access)</li> <li>&gt; Hearing Conservation Training</li> <li>&gt; Work At Height &amp; Scaffolding Training</li> <li>&gt; Waste Management &amp; Chemical Handling Training</li> </ul>	<ul style="list-style-type: none"> <li>&gt; Fire Extinguishers Training</li> <li>&gt; Breathing Apparatus Training</li> <li>&gt; Basic First Aid Training</li> <li>&gt; Medical Clearance Certificate (Must be approved/accepted by ORYX GTL's Health Center)</li> </ul>	PTW-1 (Site Supervisor) PTW-2 (Permit Receiver)